ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0006, W0020, W0081, W0073, W0065, W0069, W0061	NA, 14th Crs, Om Shakthi Lyt 5th Crs, Om Shakthi Lyt 7th Crs	R.K.hegadenagara
Segment No.	**Total Length (m)**	
6/C-W0006/S032911	532.63	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	105.99	77.632053	13.070009	77.631077	13.069968	4th cross	7th cross 2nd main
2	426.64	77.633148	13.071739	77.633169	13.067883	R.K.Hegadenagara 1st cross	dead end

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to road and footpath in ward no. 06, Thanisandra.	7500000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	covering slab and kerb stone
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	covering slab and kerb stone	006-18-000023
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/69/2017-18	07/02/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
07/02/2018	07/02/2019	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9449863065		

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

Field Inspection Details

Number of Trees	Any Other Information	Name
0		daramsingh c naik

Date of Inspection	Remarks
20/04/2018	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	21/04/2018	19/05/2018	As proposed

Zone: YELAHANKA Ward No: 6 Ward Name: Thanisandra Street ID: W0006, W0020, W0081, W0073,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

SE	Vasu K M	20/04/2018	19/05/2018	Completed
	Mohandas H.T	20/04/2018	19/05/2018	Verify
AEE	Sridhar B.S.	20/04/2018	19/05/2018	verify
AE	Daramsingh C Naik	20/04/2018	19/05/2018	Mobile verification is done
AE	Daramsingh C Naik	19/04/2018	19/05/2018	Forwarded

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0006, W0020, W0081, W0073,